

Steel with steel pins.

2 ball bearings.

5 knuckle.

Flat button tips.

Square corner.

Supplied with full machine screws and full wood screws.

Packed in 1 1/2 pair per box.