

0" - 6" or 150mm.

LCD read out.

Push button control to convert metric to inches.

"0" reset in any position.

1.5 V long life battery included.

Data output capability for interface with host computer or printer.

Supplied with case.

Auto off.

Inside, outside & depth measurements.

Graduated slide.Large display.